

## GOLD APOLLO CO., LTD.

Rm1,3rd Fl.,No.77,Sec.1,Hsin Tai Wu Rd.,Hsi-Chih,Taipei Hsien,Taiwan, R.O.C.  
Tel : 02-2698-8888 Fax : 02-2698-1750



SUBJECT: TIMCO-TCB/Request for additional info - GOLD APOLLO CO., LTD. -  
FCC ID: NDAA07TCPU - JOB #: 1676TC13

To Whom it may concern,

The power of EUT : End user can not change/adjust the power strength.

It was fixed.

The software can adjust channel which on the range of application, it can not  
adjust power strength.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Tommy Lin', is written over a dashed horizontal line.

Tommy Lin/R&D Manager(signature)