

Report No.: FA330654

Appendix D. Test Setup Photos



Right Cheek for sample 1



Right Tilted for sample 1



Left Cheek for sample 1



Left Tilted for sample 1



Left Cheek for sample 3



Left Cheek for sample 4

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: NDPOT-300 Page Number : D1 of D3
Report Issued Date : Sep. 30, 2013
Report Version : Rev. 02





Front of the DUT with Phantom 1 cm Gap for sample 1

landauhadani



Report No.: FA330654

Back of the DUT with Phantom 1 cm Gap for sample 1



sample 1



Right Side of the DUT with Phantom 1 cm Gap for Left Side of the DUT with Phantom 1 cm Gap for sample 1



Bottom Side of the DUT with Phantom 1 cm Gap for sample 1



Back of the DUT with Phantom 1 cm Gap for sample 3

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: NDPOT-300

Page Number : D2 of D3 Report Issued Date: Sep. 30, 2013 Report Version : Rev. 02





Back of the DUT with Phantom 1 cm Gap with earphone for sample 3



Report No.: FA330654

Back of the DUT with Phantom 1 cm Gap for sample 4



Back of the DUT with Phantom 1 cm Gap with earphone for sample 4



Back of the DUT with Phantom 0 cm Gap with earphone for sample 3



Back of the DUT with Phantom 0 cm Gap with earphone for sample 4

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: NDPOT-300

Page Number : D3 of D3 Report Issued Date: Sep. 30, 2013 Report Version : Rev. 02