

Prüfbericht - Nr.:
Test Report No.


1403929 002

Seite 1 von 2
Page 1 of 2

4374

FS

Ref




Date: 24.JUL.2003 20:01:02

Prüfbericht - Nr.:
Test Report No.

1403929 002

Seite 2 von 2
Page 2 of 2

4374



Date: 24.JUL.2003 20:17:45

26 dB down from carrier:

- Marker 2 : 49.8416 MHz
- Marker 3 : 49.8752 MHz