


Prüfbericht - Nr.:
Test Report No.

14010953 001

Seite 1 von 4
Page 1 of 4



MES TUV260505A04.PK
LIM FCC P15.109 Class B


Page 1 5/26/05 6:49PM

H
9436 R. Stubby

Prüfbericht - Nr.:
Test Report No.

14010953 001

Seite 2 von 4
Page 2 of 4




MES TUV260505A03.PK
LIM FCC P15.109 Class B

Prüfbericht - Nr.:
Test Report No.

14010953 001

Seite 3 von 4
Page 3 of 4



MES TUV260505A02.PK
LIM FCC P15.109 Class B


Page 1 5/26/05 6:25PM

H
4956 Rx Sandy

Prüfbericht - Nr.:
 Test Report No.

14010953 001

Seite 4 von 4
 Page 4 of 4



MES TUV260505A01.PK
 LIM FCC P15.109 Class B

Page 1 5/26/05 6:12PM

V
 94% Rx Standby