

Conducted Test Setup Placement:



Front View of the Test Configuration



Side View of the Test Configuration


FCC ID: NHPWLB1402

Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440

Radiated Test Setup Placement: (Unintentional)



Front View of the Test Configuration of Unintentional



Rear View of the Test Configuration of Unintentional

Radiated Test Setup Placement: (Intentional)



Front View of the Test Configuration of Intentional



Rear View of the Test Configuration of Intentional

FCC ID: NHPWLB1402

Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440