



### **APPENDIX 3: Photographs of test setup**

#### **Radiated Emission**



**Photo 1**



**Photo 2**

**Worst Case Position**

**ECU**  
 Below 30 MHz  
 X-axis  
 Above 30 MHz  
 Horizontal: X-axis / Vertical: X-axis  
 X-axis




**Y-axis**



**Z-axis**




**Outside ANT**  
 Below 30 MHz  
 Z-axis  
 Above 30 MHz  
 Horizontal: X-axis / Vertical: X-axis  
 X-axis



**Y-axis**



**Z-axis**




**Worst Case Position**

**Trunk ANT**  
Below 30 MHz  
X-axis  
Above 30 MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis




**Y-axis**




**Z-axis**




**Room ANT**  
Below 30 MHz  
X-axis  
Above 30 MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis



**Y-axis**



**Z-axis**



**End of Report**

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124