

TOYOTA

TOYOTA MOTOR CORPORATION

1, TOYOTA-CHO, TOYOTA, AICHI, 471-8571 (Head Office)
or 471-8572 (Research & Development Group) JAPAN
TEL : +81-565-28-2121

Industry Canada
Certification & Engineering Bureau
3701 Carling Avenue, Bldg. 94
Ottawa, Ontario
K2H 8S2, CANADA

Date: May 22, 2008

Subject: Compliance Statement in Car manual IC:2842A-TMLF82

Dear Sirs,


Our products with the above IC ID codes are low-frequency transmitters. The products will have been installed in cars before they are placed into the market.

We hereby assure that the following caution statement as per RSS GEN § 7.1.5 is included in the owner's manuals of the cars:

Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Yours sincerely,



Takaaki Enomoto
Toyota Motor Corporation
Telephone Number: +81-565-94-1007
Fax Number: +81-565-94-1192