





2.7 PHOTOS OF CONDUCTION TEST



(1) For Printer port





2.7 PHOTOS OF CONDUCTION TEST

(2) For USB port





3.7 PHOTOS OF OPEN SITE

(1) For Printer port





Industrial Technology Research Institute

Electronics Research & Service Organization

Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310

Taiwan, Republic Of China

TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : NJCDP36VC

Report No. : ESM-8806-002F

Page 18 of 20

3.7 PHOTOS OF OPEN SITE


(1) For Printer port





3.7 PHOTOS OF OPEN SITE

(2) For USB port





Industrial Technology Research Institute
Electronics Research & Service Organization
Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : NJCDP36VC

Report No. : ESM-8806-002F

Page 20 of 20

3.7 PHOTOS OF OPEN SITE

(2) For USB port

