



Feb. 23, 1999

Dear Sirs / Madam □

The manufactor, Compeye Corp., has changed several components in their scanner (FCC ID □ NJCDP66V) but their wish to continue using the same FCC ID. the changed parts are listed below □

CCD Board □

1. The CCD (ILX535K) has been changed as CCD(ILX540M/ILX540K)
2. The CCD Board has been re-layouted.
3. The tantalum capacitors on CCD Board have been changed as electrolytic capacitors.

Main Board □

1. The Tantalum capacitors on main Board have been changed as electrolytic capacitors.

The changes were made only in those units produced after those changes are authorized. We have already tested the modified product and attached the test report. If you have any question, please contact with us.

Thanks you very much.

Yours faithfully,

Miranda Chen

ERSO/ITRI