

Mike Kuo

From: daphne.liang [daphne.liang@tw.ccsemc.com]
Sent: Monday, January 02, 2006 10:09 PM
To: Mike Kuo; application@tw.ccsemc.com
Cc: lucy.tsai
Subject: Re : FW: Billinton Systems Inc., FCC ID: NLF-GUBTCR4XX, Assessment NO.: AN05T5387, Notice#1-- Updated(0103)
Importance: High
Attachments: GUBTCR4XT-XX-YYY_Internal Photo(0103).pdf; GUBTCR41T-XX-YYY_Report(RP1-1)0103.pdf; GUBTCR4XT-XX-YYY_Manual(0103).pdf; GUBTCR4XT-XX-YYY_Confidentiality Letter(0103).pdf; GUBTCR4XT-XX-YYY_Label Location(0103).pdf; GUBTCR41T-XX-YYY_Setup Photo(0103).pdf

Dear Mike:

Thank you for your e-mail. Please see the belowing reply and find the updated files(0103) as attached.

Also please note that our client has changed their model name as: GUBTCR4XT-XX-YYY; GUBTCR4XU-XX-YYY
I have updated other necessary documents as attached.

If still have any problems, please let me know, thank you for your support~

BEST REGARDS

Daphne Liang / 梁鈺如 01/03/2006
Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc.
Rm.258, Bldg.17, No.195, Sec.4, Chung
Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.
Tel: 886-3-5910068 EXT: 502
Fax: 886-3-5825720
E-mail: daphne.liang@tw.ccsemc.com
URL: <http://www.ccsemc.com.tw>

lucy.tsai

蔡文君

收件人: daphne_liang/ccsemc

副本抄送:

主旨: FW: Billinton Systems Inc., FCC ID: NLF-GUBTCR4XX, Assessment NO.: AN05T5387, Notice#1

2006/01/02 05:27 PM

----- 轉呈者 lucy.tsai/ccsemc 於 2006/01/02 05:20 PM -----

"Mike Kuo"

<mike.kuo@ccsemc.com>

收件人: <vanessa.tasi@ccsemc.com.tw>, "application" <application@tw.ccsemc.com>,

<vanessa.tasi@tw.ccsemc.com>

1/3/2006

2005/12/28 04:00 AM

副本抄送: "lucy.tsai" <lucy.tsai@tw.ccsemc.com>

主旨: FW: Billionton Systems Inc., FCC ID: NLF-GUBTCR4XX, Assessment NO.: AN05T5387, Notice#1

Question #1: Please remove the plastic housing and take internal photos on the PCB component side and solder side.

Ans: Please find the attach for updated Internal phtot(0103).

Question #2: Section 2 under remark section of test report, the FCC ID number listed does not agree with proposed FCC ID number. Please make necessary correction.

Ans: Please find the attach for updated test report(0103) of page 5.

Question #3: Based upon the screen shots contain in the user manual, submitted user manual is written for Toshiba but Toshiba is not one of manufacturer listed in the multiple listing section. In addition, most of screen shots are not clear, please make sure to submit a clear version of user manual.

Ans: Please find the attach for updated User manual(0103).

Question #4: User manual does not contains information required per section 15.21 of FCC rules. In addition, since this device is equipped with USB connector which is also subject to FCC Part 15 subpart B as digital Class B device. Statement listed in section 15.105(b) is also required. If digital portion is subject to FCC DoC procedures, the labeling requirement per section 15.19 must be included in the label format as well.

Ans: Please find the attach for updated User manual(0103) of page 160.

Question #5: Device is capable of various data rate, which data rate was selected for the final tests and justification of the worst case.

Ans: Please find the attach for updated test report(0103).

Since our client's software can not support any more even the Air Data Rate in specification is up to 8-DPSK (3Mbps)!!

So we measurement the Air Data Rate is GFSK (1Mbps) and selected for the final tests.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an

1/3/2006

identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.