Appendix A. Test Photos

 SPORTON International Inc.
 Page No.
 : A1 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Dec. 20, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : NLFGMEWLGRL-2

1. Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 Page No.
 : A2 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Dec. 20, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : NLFGMEWLGRL-2



SIDE VIEW


 SPORTON International Inc.
 Page No.
 : A3 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Dec. 20, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : NLFGMEWLGRL-2

2. Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW

 SPORTON International Inc.
 Page No.
 : A4 of A7


 TEL: 886-2-2696-2468
 Issued Date
 : Dec. 20, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : NLFGMEWLGRL-2

For radiated emissions 30MHz~1GHz




FRONT VIEW




REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : A5 of A7
Issued Date : Dec. 20, 2007
FCC ID : NLFGMEWLGRL-2

For radiated emissions above 1GHz



FRONT VIEW




REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : A6 of A7
Issued Date : Dec. 20, 2007
FCC ID : NLFGMEWLGRL-2

Test Fixture



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

Page No. : A7 of A7
Issued Date : Dec. 20, 2007
FCC ID : NLFGMEWLGRL-2