

## Response to TCB Findings

Please confirm that the ferrites added as a modification to the Ethernet and power cables are inside the equipment cover when supplied to the installers. In other words, installers will not be adding these to the device at the time of installation. If that's the case the user's manual will need appropriate warnings to the installers about this ferrites.

*As per the client: "The ferrites are being added to the manufacturing documentation and will be installed in each unit prior to shipment to the installer."*