FCC TEST REPORT Report No. : F362011

## 1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 




**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : NM8HB25I
Page No. : 1 of 3
Issued Date : Jul. 21, 2003

FCC TEST REPORT Report No. : F362011



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : NM8HB25I

 TEL: 886-2-2696-2468
 Page No.
 : 2 of 3

 FAX: 886-2-2696-2255
 Issued Date
 : Jul. 21, 2003

FCC TEST REPORT Report No.: F362011

## 1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : NM8HB25I
Page No. : 3 of 3
Issued Date : Jul. 21, 2003