


## Report No.: FA141115-01B

## Appendix D. Test Setup Photos





**Right Cheek** 





Left Cheek

**Right Tilted** 



**Left Tilted** 




Front Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: NM8PG58110 Page Number : D1 of D2
Report Issued Date : May 31, 2011

Report Version : Rev. 01






Rear Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Report No.: FA141115-01B

Rear Face of the DUT with Phantom 1 cm Gap (DUT with Earphone)



Left Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Right Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Top Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: NM8PG58110 Page Number : D2 of D2 Report Issued Date: May 31, 2011 Report Version : Rev. 01