


## Appendix D. Test Setup Photos





Report No.: FA132949C

**Right Cheek** 









Left Cheek Left Tilted

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: NM8PH44100 Page Number : D1 of D2
Report Issued Date : May 20, 2011
Report Version : Rev. 01




Front Face of the DUT with Phantom 1 cm Gap for DUT without Earphone



Report No.: FA132949C


Rear Face of the DUT with Phantom 1 cm Gap for DUT without Earphone



Rear Face of the DUT with Phantom 1 cm Gap for DUT with Earphone



Left Side of the DUT with Phantom 1 cm Gap for DUT without Earphone



Right Side of the DUT with Phantom 1 cm Gap for DUT without Earphone



Top Side of the DUT with Phantom 1 cm Gap for DUT without Earphone

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: NM8PH44100 Page Number : D2 of D2
Report Issued Date : May 20, 2011
Report Version : Rev. 01