




<i>Company Name:</i>	<i>Samsung Telecommunications America</i>
<i>FCC ID:</i>	<i>NP8-1900-10-PRU</i>
<i>Work Order Number</i>	<i>2000034 / A0398</i>

APPENDIX B:

OCCUPIED BANDWIDTH PLOTS




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B1: OCCUPIED BANDWIDTH CHANNEL 150 BLK A




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B2: OCCUPIED BANDWIDTH CHANNEL 350 BLK D




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B3: OCCUPIED BANDWIDTH CHANNEL 550 BLK B




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B4: OCCUPIED BANDWIDTH CHANNEL 750 BLK E




Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B5: OCCUPIED BANDWIDTH CHANNEL 850 BLK F



Company Name:	Samsung Telecommunications America
FCC ID:	NP8-1900-10-PRU
Work Order Number	2000034 / A0398



B6: OCCUPIED BANDWIDTH CHANNEL 1050 BLK C