

Tx

Report No.: 9807849


Tested By: Hong, Report No.: 9807849

Scan Settings (1 Range)  
 |----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QF  
 Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078



Ctrl. No.: N/A

**ITS** Intertek Testing Services  
ETL Testing Laboratories

Report No.: 9807849

Tx

Tested By: Hong, Report No.: 9807849

Scan Settings (1 Range)

```
|----- Frequencies -----|----- Receiver Settings -----|  
Start      Stop      Step      IF BW  Detector  M-Time  Atten  Preamp  OpRge  
450k      30M      5k       10k   PK       20ms  AUTO  LN  OFF  60dB
```

Final Measurement Results:

no Results

Ctrl. No.: N/A

*Stand-by*


Report No.: *9807849*

Tested By: Hong, Report No.: 9807849

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamplifier	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement:	x	QP	Transducer No.	Start	Stop	Name
Meas Time:	1	s	3	9k	30M	E1078
Subranges:	16					
Acc Margin:	20dB					



Ctrl. No.: *N/A*

Report No.: 9807849

*Stand-by*

Tested By: Hong, Report No.: 9807849

Scan Settings (1 Range)

```
|----- Frequencies -----|----- Receiver Settings -----|
Start      Stop      Step      IF BW  Detector  M-Time  Atten  Preamp  OpRge
450k      30M      5k        10k   PK        20ms  AUTO  LN  OFF  60dB
```

Final Measurement Results:

no Results

Ctrl. No.: N/A

Report No.: 9807808


*Charging*

Tested By: Hong, Report No.: 9807849  
 Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP  
 Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No. Start Stop Name  
 3 9k 30M EI078



Ctrl. No.: N/A

# ITS Intertek Testing Services

ETL Testing Laboratories

Report No.: 9807849

*Charging*

Tested By: Hong, Report No.: 9807849

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A