



# Intertek Testing Services

ETL Testing Laboratories

Mode = TX

Report No.: 9809825

Tested By: Hong, Report No.: 9809825


Scan Settings (1 Range)

Frequencies				Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	

Final Measurement: N QP

Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl. No.: N/A

# ITS Intertek Testing Services

ETL Testing Laboratories

Mode = TX

Report No.: 9809825

Tested By: Hong, Report No.: 9809825

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



# Intertek Testing Services

ETL Testing Laboratories

Mode = Standby

Report No.: 9809825

Tested By: Hong, Report No.: 9809825


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QP

Transducer No.	Start	Stop	Name
2	9k	30M	EI078

Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB



Ctrl. No.: N/A

# ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Stand by

Report No.: 9809825

Tested By: Hong, Report No.: 9809825

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

# ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Charging

Report No.: 9809825


Tested By: Hong, Report No.: 9809825

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: 2 QP  
 Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB



Ctrl. No.: N/A

# ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Charging

Report No.: 9809825

Tested By: Hong, Report No.: 9809825

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A