

Report No.: 9901556


Mode = TX

Tested By: Hong, Report No.: 9901556

Scan Settings (2 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamplifier
450K	30M	5K	10K	PK	20ms	AUTO	LN OFF 60dB

Final Measurement: N OP	Transducer No.	Start	Stop	Name
	2	9K	30M	BI078
Meas Time: 1 s				
Subranges: 16				
Acc Margin: 20dB				



Ctrl. No.: N/A

Report No.: 9901556

Mode = TX

Tested By: Hong, Report No.: 9901556

Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	

Final Measurement Results:

no Results

Ctrl. No.: N/A