



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9901060


Tested By: Hong, Report No.: 8901060

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PR	20ms	AUTO	LN OFF	60dB

Final Measurement: X QF	Transducer No.	Start	Stop	Name
	3	9k	30M	81078

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB



Ctrl. No.: N/A

Report No.: 9901060

Tested By: Hong, Report No.: 9901060

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A