



Allflex USA, Inc.

P.O. Box 612266 • 2805 East 14th Street • Dallas/Ft Worth Airport, Texas 75261-2266 • USA
Telephone: (972) 456-3686 • Facsimile: (972) 456-3882

Federal Communications Commission
Authorization and Evaluation Division
1435 Oakland Mills Road
Columbia, MD 21046

Date: 13 NOV 2018

SUBJECT: FCC request change of GRANT

To Whom It May Concern:

We understand that an error was made on 1 of our GRANT request. We request the dismissal of job 1050BFC18 , FCC ID: NQYTEI-30014. TCB, Timco accidentally included "TEI" in the FCC ID upon uploading the application. The FCC ID should not include "TEI". The email field where email address "TEI@TIMCOENGR.COM" is right below the FCC ID equipment product code field and unintentionally included TEI in the FCC ID's equipment product code. Furthermore, no units were marketed or sold with FCC ID: NQYTEI-30014 anywhere in the world.

Regards,
Simon Alfaro, Technical Manager, NA

A handwritten signature in black ink, appearing to be "S Alfaro", written in a cursive style.