



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9903008

Mode: Charging

Tested By: Hong, Report No.: 9903008


Scan Settings (1 Range)

Frequencies		Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10K	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: 0 QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9K	30M	EI078



Ctrl. No.: N/A

Report No.: 9903008

Mode: Charging

Tested By: Hong, Report No.: 9903008

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
27.87500	28.1	48.0

* limit exceeded

Ctrl. No.: N/A



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9903008
Mode: Standby

Tested By: Hong, Report No.: 9903008


Scan Settings (1 Range)

Frequencies		Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: X QP

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl. No.: N/A



Intertek Testing Services

ETL Testing Laboratories

Report No.: 7903008

Made Standby

Tested By: Hong, Report No.: 9903008

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
27.87500	27.7	48.0

* limit exceeded

Ctrl. No.: N/A



Report No.: 9903008


Made: Transmission

Tested By: Hong, Report No.: 9903008

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	50dB

Final Measurement:	Transducer No.	Start	Stop	Name
X_QP	3	9k	30M	EI078
Meas Time: 1 s				
Subranges: 16				
Acc Margin: 20dB				



Ctrl. No.: N/A



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9903008

Mode: Transmission

Tested By: Hong, Report No.: 9903008

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A