



Intertek Testing Services

ETL SEMKO

Report No.: 9904580
 Mode: Charging

Tested By: Hong, Report No.: 9904580


Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10K	PK	20ms	AUTO	LN	OFF	60dB

Final Measurement: NQP

Transducer No. Start Stop Name
 3 9k 30M EI078

Meas Time: 1 s
 Subranges: 16
 Acc Margin: .20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904580

Tested By: Hong, Report No.: 9904580

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services


ETL SEMKO

Report No.: 9904580
Mode: Standby

Tested By: Hong, Report No.: 9904580
Scan Settings (1 Range)

Frequencies		Receiver Settings						
Start	Stop	Stop	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: \times QP
Transducer No. Start Stop Name
3 9k 30M EI078
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904580

Mode: Standby

Tested By: Hong, Report No.: 9904580

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904580

Mode: Transmission

Tested By: Hong, Report No.: 9904580


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QF

Transducer No.	Start	Stop	Name
3	9k	30M	E1078

Meas Time: 1 s
 Subranges: 16
 Acc Margin: -20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904580

Mode: Transmission

Tested By: Hong, Report No.: 9904580

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A