



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395

Mode 1 Charging

Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

Frequency		Receiver Settings							
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	50k	PK	20ms	AUTO	LN	OFF	60dB

Final Measurement: x QF


Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 15

Acc Margin: 20dB

dBuV



PAGE 1

Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395

Mode: Charging

Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK.	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395  
*Made: Standby*


Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

Frequencies		Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Presamp	OpRge
450k	30M	5k	10k	PK	CGas	AUTO	LN	OFF
								60dB

Final Measurement: X GP  
 Meas Time: 1.8  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No. Start Stop Name  
 3 9k 30M EI078



Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395

Mode: Standby

Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395

Mode: Transmission


Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	H-Time	Atten	Preamp	OpRge
450k	30M	5k	10K	PK	Auto	LN	OFF	50dB

Final Measurement: S QP  
 Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No. Start Stop Name  
 3 9k 30M EI078



Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 9903395

Made: *Transmission*

Tested By: Hong, Report No.: 9903395

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A