



Intertek Testing Services

ETL SEMKO

Report No.: 9904647
 Mode: Charging

Tested By: Hong, Report No.: 9904647


Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|---------|----------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Presamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN | OFF 60dB |

Final Measurement: N QP

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB

| Transducer No. | Start | Stop | Name |
|----------------|-------|------|-------|
| 3 | 9k | 30M | SI078 |



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904647

Mode: Charging

Tested By: Hong, Report No.: 9904647

Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904647

Mode: Standby

Tested By: Hong, Report No.: 9904647

Scan Settings (1 Range)

| Frequencies | | | | Receiver Settings | | | |
|-------------|------|------|-------|-------------------|--------|-------|--------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF |


Final Measurement: X QF

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

| Transducer No. | Start | Stop | Name |
|----------------|-------|------|-------|
| 3 | 9k | 30M | EI078 |



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904647

Mode: Standby

Tested By: Hong, Report No.: 9904647

Scan Settings (1 Range)

| ----- Frequencies ----- | | | ----- Receiver Settings ----- | | | | | |
|-------------------------|------|------|-------------------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904647

Mode: Transmission

Tested By: Hong, Report No.: 9904647

Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement: X OP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

3 9k 30M EI078



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904647

Mode: Transmission

Tested By: Hong, Report No.: 9904647

Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: N/A