#110, 1144 - 29th Avenue N.E. Calgary, Alberta T2E 7P1 Tel: (403) 248-0028

Fax: (403) 248-2762 Website: http://www.microhardcorp.com

FCC ID: NS900P4

June 14, 2002

Federal Communications Commission OET Laboratory Division. 7435 Oakland Mills Rd. Columbia, MD 21046

Re: Overview of Engineering Changes

The following are an overview of the changes made to the MHX-2400:

Use MCX or Reverse SMA connector
Digital Temperature compensation option
Reset circuit for microprocessor
Inner shield for VCO circuit
VCO buffer circuit changed with compatible part.
Output Match Optimized
PA DAC changed vendors
Added Antennas to test set

Please note that the Bill of Material and Schematics have been updated to reflect these changes.

Regards,

Hany H. Shenouda

Director of Engineering

Harry A Sherry