



Communication Components, Inc.
89 Leuning Street Phone: 201-342-3338
South Hackensack, NJ 07606 Fax: 201-342-3339

Tune up Procedure

There is no tune up procedure for the CCI# BDA-1819-10. It is simply a bi-directional repeater with a fixed gain linear power amplifier and a low noise amplifier. Any gain adjustments are to be performed utilizing an external attenuator.

All necessary repairs and adjustments are performed at the factory.

Dated this 25 Day of July 20 08

By:

Dennis Nathan

Signature

Printed

Title: President

On behalf of: Communication Components Inc.