

Communication Components, Inc.

89 Leuning Street Phone: 201-342-3338 Fax: 201-342-3339

South Hackensack, NJ 07606

Tune up Procedure

There is no tune up procedure for this system. It is simply an ultra-linear multi-carrier power amplifier with a fixed pass band RF filter.

All necessary repairs and adjustments are performed at the factory.

Dated	this <u>22</u> Day of <u>Ja</u>	nuary 20 <u>07</u>
Ву:	Dennil Valla	Dennis Nathan
_	Signature	Printed
Title:	President	
On be	half of: Communicatio	n Components Inc.