




Communication Components, Inc.  
89 Leuning Street Phone: 201-342-3338  
South Hackensack, NJ 07606 Fax: 201-342-3339

### **Tune up Procedure**

There is no tune up procedure for the CCI# MCPA2100-125. It is simply a single input, single output, multicarrier amplifier with a self-contained linearizer control loop. Any gain adjustments are to be performed utilizing an external attenuator.

All necessary repairs and adjustments are performed at the factory by trained personnel.

Dated this 3rd Day of February 20 11

By:  Dennis Nathan  
Signature Printed

Title: President

On behalf of: Communication Components Inc.