




Communication Components, Inc.
89 Leuning Street Phone: 201-342-3338
South Hackensack, NJ 07606 Fax: 201-342-3339

SCB-850-1W-ALU-OD-1 Tune up Procedure

There is no tune up procedure for the CCI# SCB-850-1W-ALU-OD-1. It is simply a single input, single output, single channel full duplex amplifier with a second Rx diversity / Tx bypass channel. Any gain adjustments must be performed by utilizing an external attenuator.

All necessary repairs and adjustments are performed at the factory by trained personnel.

Dated this 07th Day May of 20 14

By:  Dennis Nathan
Signature Printed

Title: President

On behalf of: Communication Components Inc.