



HERMON LABORATORIES

February 3, 2004

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated January 27, 2004; Telematics Wireless Ltd.
FCC ID:NTAFP100RA, ATCB001034

Dear Mr. Johnson,
Please find below the answers to your questions.

General Requirements

- 1) The maximum output power from the power amplifier is +28 dBm. However due to R/T switch and LPF attenuation, there is a loss of 1.8 dB from the power amplifier output to the antenna connector, yielding a maximum output power of +26.2 dBm.
We apologize for printed mistake in paragraph 4 of our reply dated January 22, 2004 – the worst case is +26.2 dBm.

Part 90 Requirements

- 2) The device should be categorized as fixed.

Part 15 Requirements

- 3) Conducted emissions testing was performed. The revised test report TELRAD_FCC.15717_rev3 was uploaded on February 3, 2004.

Thank you.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories