

FCC ID:NTAFP310RAM-X, output power control

The power level is not tunable. The power level may vary from unit to unit between +16 dBm to +18 dBm. This variation is caused by tolerance of components values and battery voltage.

Sincerely,

Itsik Kanner
RF group Manager