



HERMON LABORATORIES

November 22, 2005

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated November 16, 2005; Telematics Wireless Ltd.
FCC ID:NTAXMETER30, ATCB002948

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The corrected Block diagram_16716_rev1, ATCB Form 731_16716_rev1, test report TELRAD_FCC.16716_rev1 were uploaded on November 23, 2005.
- 2) The TELRAD_FCC.16716_rev1 with corrected page 6 .
- 3) The corrected file "Operational_description_16716_rev1" was uploaded on November 23, 2005.
- 4) Please refer to corrected test report TELRAD_FCC.16716_rev1.
- 5) The file "Attachment_test-report_16716" with our explanation was uploaded on November 23, 2005 via Test Report folder.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories