



HERMON LABORATORIES

November 28, 2005

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated November 23, 2005; Telematics Wireless Ltd.  
**FCC ID:NTAXMETER30, ATCB002948**

Dear Mr. Johnson,  
Please find below the answers to your questions.

- 1) The file "Attachment2\_test-report\_16716" with plot 7.3.26 explanation was uploaded on November 28, 2005 via Test Report folder.
- 2) The revised test report with corrected page 25, file "TELRAD\_FCC.16716\_rev3" (rev2 was uploaded by mistake) was uploaded on November 28, 2005 via Test Report folder.  
The RBW=1000 kHz is shown in page 24 before the table and in plots (e.g. 7.3.69, 7.3.70).  
Table on page 25 corrected for VBW=3 MHz in peak and VBW=1 kHz in average (also refer to plots, e.g. 7.3.69, 7.3.70, 7.3.73, 7.3.74 etc).

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories