FCC TEST REPORT Report No.: F392203

1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468


FAX: 886-2-2696-2255

FCC ID : NUKWBRISW0504

Page No. : 1 of 3

Issued : Oct. 29, 2003

FCC TEST REPORT Report No.: F392203




SIDE VIEW

SPORTON International Inc. FCC ID : NUKWBRISW0504


TEL: 886-2-2696-2468 Page No. : 2 of 3 FAX: 886-2-2696-2255 Issued : Oct. 29, 2003 FCC TEST REPORT Report No.: F392203

1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. FCC ID : NUKWBRISW0504

TEL: 886-2-2696-2468 Page No. : 3 of 3 FAX: 886-2-2696-2255 Issued : Oct. 29, 2003