



Training Research Co., Ltd

No. 2, Lane 194, Huan-Ho St., Hsichih, Taipei Hsien 221, Taiwan, R.O.C.

TEL:886-2-26935155 FAX:886-2-26934440

E-mail:report@trclab.com.tw

January 25, 2002

RE: American Telecommunications Certification Body Inc.
FCC ID: NUSTMW1003

Dear William:

After the review of your comments we'd received on the yesterday, we've made some modifications upon your advice; the modifications are summarized as follows:

1. The RF Expose report has been solved the *R* already, it's represent the distance between the center of radiation of the antenna. Anyway we resubmit again more clearly.
2. We will suggest the manufacturer to modify the manual, see the attachment.
3. The label is modified, please find these in the attachment.
4. We have uploaded the Test Setup Photo as a separate file. Please find them in the attachment.
5. The Access Point doesn't comply with the hand-held or body-worn devices defined in the ANSI C63.4-1992, Sect.13.1.4.1 (3). Therefore tests needed not to perform in the manner for the hand-held such as tested in 3-orthogonal plane.

The matters needed with the modified report are attached.

Should you have any questions, please feel free to contact us. Thanks for your kindly consideration.

Sincerely yours,
Eric Wong
Testing Engineer
Training Research Co Ltd.