

May 17, 1999

Dear Sir / Madam:

We would like to inform FCC that there was a typing error in the FCC ID for this product's application. The correct FCC ID is :

NV6FRS100 instead of NV6FR100.

We would like to sincerely apologise for such mistake and would like to ask for your kind cooperation in making this change.

Yours Faithfully,

Liza Chan
Engineer
Intertek Testing Services Hong Kong Ltd.