

Coverletter:

Submitting of requested information for FCC-ID: NXWMOBYU-MDSU313

List of documents:

Question	Theme	Response
1	Field strength in grant	Removed
2	Equipment class	Corrected
3	Label	Corrected in file: MDS 313.pdf
4	Letter requesting confidentiality	Corrected in file: REQUEST FOR CONFIDENTIALITY.doc
5	Internal photos	No more applicable
6	Testing on three frequencies	See test report-file: 03-101.pdf and setup03-101.pdf for photos
7	Measurement to the 10 th harmonic	See test report-file: 03-101.pdf and setup03-101.pdf for photos
8	Antenna requirement according to 15.203	The Antenna(e) are permanently attached to the PCB by soldering.
9	Peak values	See test report-file: 03-101.pdf and setup03-101.pdf for photos
10	Separate tests and reports	See test report-file: 03-101.pdf and setup03-101.pdf for photos
11	Test signal	See test report-file: 03-101.pdf and setup03-101.pdf for photos
12	Identical files	corrected

Additional information to the user manual: Beiblatt_Manual.doc