

## Coverletter:

Siemens Österreich AG wants to get a Class II permissive change to a former FCC-Certification for the product with the FCC-ID: NXWMOBYU-SLGU92-0 because of discontinuation of older components:

List of documents:

<b>Exhibit</b>	<b>Thema</b>	<b>File</b>
Exhibit 01	Label and placement	label_10-133.pdf
Exhibit 02	Not needed	-----
Exhibit 03	External Photos	extern_10-133.pdf
Exhibit 04	Block Diagrams	-----
* Exhibit 05	Schematic Diagrams	A97238-Q3071-B8-6-7411.pdf Deltalist_Circuit_Diagrams_20100909.pdf
Exhibit 06	Testreport	10-133.pdf
Exhibit 07	Test Set-up Photos	setup_10-133.pdf
Exhibit 08	User Manual	-----
Exhibit 09	Internal Photos	intern_10-133.pdf
Exhibit 10	Informations	-----
Exhibit 11	RF exposure	-----
Exhibit 12	Operational Description	-----
Exhibit 13	Cover letter	This file

For the Exhibits marked with “\*” Siemens Österreich AG requested Confidentiality according to 47 CFR 0.457 and 0.459 of the FCC rules because these are sensitive parts owned by this company and include much of Know-How or sensitive data, it will not be provided to the public.