

Coverletter:

Submitting of requested information for FCC-ID: NXWMOBYU-SLGU92-1

List of documents:

Question	Theme	Response
1	Field strength in grant	Removed
2	Equipment class	Corrected
3	Label	Corrected in file: SLG 232.pdf
4	Letter requesting confidentiality	Corrected in file: REQUEST FOR CONFIDENTIALITY.doc
5	Internal photos	No more applicable
6	Testing on three frequencies	See test report-file: 03-101.pdf and setup03-101.pdf for photos
7	Measurement to the 10 th harmonic	See test report-file: 03-101.pdf and setup03-101.pdf for photos
8	Antenna requirement according to 15.203	The Antenna(e) are permanently attached to the PCB by soldering.
9	Peak values	See test report-file: 03-101.pdf and setup03-101.pdf for photos
10	Separate tests and reports	See test report-file: 03-101.pdf and setup03-101.pdf for photos
11	Test signal	See test report-file: 03-101.pdf and setup03-101.pdf for photos
12	Identical files	corrected

Three components were changed from original granted model to the new tested. The changes are described as follows:

1. Changes-2003-01-23.doc Description of changes with reasons for it
2. SLG_Z_RS232.pdf New schematic diagrams
3. Beiblatt_Manual.doc Additional information to the user manual