

Software lock on WDMX TRX

To whom it may concern:

We, Interlite AB, hereby attest that the 2.4GHz functionality of this device is permanently disabled via configuration settings in the factory.

The configuration setting that disabling 2.4GHz functionality cannot be accessed by the installer or end user and is not affected by software updates performed by end user.



Anders Zellén
CTO Interlite AB

09/30/2014