

ACB:

UL has measured radiated emissions using a different modulation scheme to that used by Sulis Consultants for the rest of the measurements. Please justify the worst case configuration.

Applicant:

There is an error in the UL test report. Radiated testing was performed using the same operating mode as conducted emissions. I confirm that UL testing was performed in 256QAM mode.

ACB:

There seems to be another channel bandwidth available (5 MHz in UL test report). Please confirm if 5 MHz channel bandwidth is available.

Applicant:

Whilst the UL test report shows results for 5 MHz channels, this mode of operation is not supported, as per Operational Description which only refers to 10 MHz channels