FCC TEST ABOUT 9807 ANTENNA

(9806)

The antenna screw of 9807 is of N13.5 \times 0.6 specifications. This specification of the antenna screw is different from the common specifications found in the market M2.5 \times 0.45 and M3 \times 0.5, which are incompatible.

The antenna fixing nut in the 9807 transmitter is of M3.5 \times 0.6 specifications. This specification of the transmitter's nut is different from the common specification found in the market M2.5 \times 0.45 and M3 \times 0.5, which are incompatible

