

## Helen Zhao

---

**Subject:** FW: Youngshin Electronics Co., Ltd., FCC ID: O44J2W8000R, Assessment NO.: AN05T4454, Notice#1



IDLabel\_2W8000R.jO44J2W8000R\_Tx\_rpg



eport.pdf



O44J2W8000R  
Block.PDF

From: jmkim  
Sent: Monday, January 10, 2005 2:17 AM  
To: Helen Zhao  
Subject: Re: Youngshin Electronics Co., Ltd., FCC ID: O44J2W8000R, Assessment NO.: AN05T4454, Notice#1

> -----Original Message-----

> From: Compliance Certification Services [mailto:hzhao@ccsemc.com]

> Sent: Wednesday, January 05, 2005 4:01 PM

> To: Helen Zhao

> Subject: Youngshin Electronics Co., Ltd., FCC ID: O44J2W8000R,

> Assessment NO.: AN05T4454, Notice#1

>

>

> Question #1: Based upon FCC2.925(a)(1) "The FCC Identifier shall be preceded by the term FCC ID in capital letters on a single line." Please revise the FCC ID label format accordingly.

>

> Question #2: Page 3 of the test report indicated the frequency of the device is 433.9MHz, which does not agree with the other documents in the filing. Please revise.

>

> Question #3: Please update block diagram to correct FCC ID.

>

> Best Regards,

> Helen Zhao

>

>

> The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

>

>

>

>