



INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12061246-1

Equipment Photographs

Model: 01165

(Internal)

