



Report No.: 0008194

Tested By: Hong, Report No.: 0008194

Scan Settings (1 Range)

----- Frequencies -----|----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698 ..





# Intertek Testing Services

## ETL SEMKO

Report No.: 0008194

Tested By: Hong, Report No.: 0008194

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement Results:

no Results

Ctrl No.: N/A