

# **LIONDA TECHNOLOGY CO., LTD.**

Block 2 Laodong 2nd Industria Area, Xixian, Baoan, Shenzhen, China  
Tel.: 86-755-7917824/ 86-755-7902415, Fax: 86-755-7917944

## **DIGITAL SECURITY CODE INFORMATION**

The **GH9762/GH9763** cordless telephone has the circuitry for the digital security code system, to provide protection against unintentional access and to prevent unauthorized use of telephone line by other cordless telephone nearby. For each unit, it has a four million possible digital security code combinations. Each combination of the digital security code is randomly generated every time the handset is picked up from the base unit.

Communication between Handset and the Base unit may not be possible in any of the following situations:

1. After a power failure.
2. After relocating the Base unit by disconnecting the AC adaptor.
3. After replacing the Handset battery.
4. The Handset goes out of range from the Base unit.

To reset, place the Handset on the Base unit for 2 to 3 seconds.

**FCC ID: 063GH9762DLD02**