

Mode = Yalk

Report No.: 0012257

Tested By: Hong, Report No.: 0012257


Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpAmp
450k	30M	5k	10K	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: N GP	Transducer No.	Start	Stop	Name
	3	9k	30M	BI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Talk

Report No.: 0012257

Tested By: Hong, Report No.: 0012257

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
25.80500	28.3	48.0

* limit exceeded

Ctrl. No.: N/A