



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)

APPENDIX L: INTERNAL PHOTOGRAPHS




PHOTOGRAPH 15: INSIDE TOP CASE WITH KEYPAD PCB ATTACHED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 16: INSIDE TOP CASE WITH BOTTOM OF KEYPAD



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 17: INSIDE TOP CASE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 18: INSIDE BOTTOM OF CASE WITH RF, POWER PCB'S, AND CONNECTOR



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 19: RF PCB IN BOTTOM CASE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 20: CONNECTOR PCB IN CASE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 21: TOP OF KEYPAD PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 22: TOP OF DC POWER PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 23: BOTTOM OF DC POWER PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 24: INSIDE BOTTOM OF CASE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 25: CONNECTIONS ON MID RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 26: TAPED CONNECTIONS ON BOTTOM OF RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 27: KEYPAD SIDE OF RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 28: CONNECTIONS AT LOWER SIDE OF RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 29: CONNECTIONS AT LOWER END OF RF PCB



PHOTOGRAPH 30: RF PCB SHOWING CONNECTIONS TO KEYPAD PCB



PHOTOGRAPH 31: INSIDE BOTTOM OF HANDSET WITH COMPONENTS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 32: INSIDE TOP CASE OF HANDSET



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 33: INSIDE HANDSET SHOWING BRACE HOLDING COMPONENTS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 34: EARPIECE SPEAKER OF HANDSET




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 35: MICROPHONE AND CONNECTOR TO HANDSET



Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 37: 2 DBI ANTENNA CONNECTOR



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 38: 2 DBI ANTENNA



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 39: LABEL OF 10DBI ANTENNA



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 40: INSIDE VIEW OF 10 DBI ANTENNA



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 41: COMPONENT SIDE OF RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)




PHOTOGRAPH 42: LCD/KEYPAD SIDE OF RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 43: KEYPAD SIDE OF RF PCB WITHOUT LCD



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 44: COMPONENT SIDE OF RF PCB WITH COVER REMOVED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2002018Revision: 2
Quote Number: QRTL02-241 Revision:
FCC CFR 47 Rules and Regulations
Industry Canada Standard(s)



PHOTOGRAPH 45: COMPONENT SIDE OF RF PCB WITH SHIELDS REMOVED