

Chris Harvey

From: David Woo [David.Woo@palm.com]
Sent: Tuesday, March 06, 2007 2:25 PM
To: charvey-tcb@ccsemc.com
Cc: mike.kuo@ccsemc.com; David Woo
Subject: RE: Palm, Inc., FCC ID: O8F-895, Assessment NO.: AN07T6488, Notice#3

Attachments: Treo 755p schematics.pdf; TREO 755P T-Coil Test photos2.pdf



Treo 755p
schematics.pdf (629 .



TREO 755P T-Coil
Test photos2....

Chris,

Required items for 1 and 2 are attached. Let me know they are acceptable so we can proceed to technical compliance letter from CCS.

David

-----Original Message-----

From: charvey-tcb@ccsemc.com [mailto:charvey-tcb@ccsemc.com]
Sent: Tuesday, March 06, 2007 9:33 AM
To: David Woo
Cc: charvey-tcb@ccsemc.com; mike.kuo@ccsemc.com
Subject: Palm, Inc., FCC ID: O8F-895, Assessment NO.: AN07T6488, Notice#3

David, I have reviewed the updated and repaired files and still have the following issues that need to be addressed:

1. The Schematic Diagram exhibit is still incomplete. The text on the diagram indicates that there should be 34 sheets to the exhibit. The exhibit submitted only contains 23 pages, and the RF Circuitry is not included. Please provide the complete schematic including the RF circuits.
2. The T-Coil report submitted does not include the test setup photos or plots. Please include this required information for the T-Coil report.

Please call me and leave a message once you respond to this e-mail in light of the e-mail troubles we have had recently.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Chris Harvey
charvey-tcb@ccsemc.com